

## STATE BOARD OF HEALTH

INDIANAPOLIS

OFFICE MEMORANDUM

TO: Robert D. Malone  
Enforcement Section

FROM: Timothy J. Miller *TJM* 4/10/86  
Geology Section

SUBJECT: Johnson Controls  
IND 009549593

DATE: April 10, 1986

THRU: Karyl K. Schmidt *KS* 4/14/86  
Jack C. Corpuz *JC* 4/14/86  
Thomas L. Russell *TR* 4/15/86

EPA Region 5 Records Ctr.



305947

I have reviewed the information pertaining to Johnson Controls and their nonauthorized discharge, received October 2, 1985, and have found that Johnson Controls should perform more testing to ascertain that groundwater contamination has not occurred.

Johnson Controls should drill four borings surrounding the area of the release to a depth of 20 feet. They should sample the soil at every five-foot interval and analyze for the constituents as before. They should follow correct sampling procedures and submit the confirmation of implementation of those procedures, along with detailed drilling logs and the soil analyses to this section for evaluation.

The geology section will then evaluate the newly-submitted information and make a determination as to whether or not groundwater monitoring will have to be executed. Johnson Controls may contact this section for clarification of any of the above-mentioned objectives.

TJM/tjd